

BlueShaper[®]

RPM: 500
TORQUE: 4

TAPER

Ø

Z5



6-5%

0,30

Z6



5-4%

0,40

Z7



5-4%

0,50

GENERAL CHARACTERISTICS

Continuous rotating • Integrated conductivity • Pink & Blue heat treatment

BlueShaper[®]

Z1-Z4
Basic sequence
 (85% of cases)

Z5-Z7
If necessary
 (15% of cases)



KFile
#10

Glide Path



Z1 **Z2**

RPM: 500
Torque: 4

Shaping



Z3 **Z4** **Z5** **Z6** **Z7**

RPM: 500
Torque: 4

Finishing



Irrigate, recapitulate with
 a 10 file and re-irrigate
 after removing each
 rotary file